

LEARJET

55/60 CABIN WINDOWS



Cabin Window

Part Number

LA6600405-30 (Aft RH)

LA6600405-31 (Aft LH)

LA6600405-32 (Cabin)

Also available Undrilled

Available for: 55 and 60 Series Aircraft

*Includes Installation hardware, Installation instructions
and an extended warranty.*

FAA / PMA Approved
Available for Immediate Delivery
High Quality-Low Cost



Part Numbers for Reference Only

Authorized Canadian Distributor for



FAA/EASA REPAIR STATION

SERVICES

As the industry leader in transparencies, Lee Aerospace has been operating a full service manufacturing and repair facility since 1989. Our team of Certified Window repairmen can inspect every window in your aircraft and provide you with an expert, detailed evaluation on the condition of your aircraft windows.

As the OEM for some of the largest aircraft manufacturers in the world, Lee Aerospace qualified team of FAA certified technicians can provide you with a detailed inspection, quick repair turn around, or accurately installed windshield or window.

24-Hour AOG Service

Pre-Buy Inspection Repair Installation

FAA Certified Repair Station #YLIR863L

EASA Approved Repair Station #145.4630

FAA Certified Drug/Alcohol Program

Hangarkeepers Insurance

